


Delphi Technologies, Inc., Troy, Mi





Delphi Technologies, Inc., Troy, Mi




FIG. 2





Delphi Technologies, Inc., Troy, Mi




FIG. 3A





FIG. 3B



Delphi Technologies, Inc., Troy, Mi






FIG. 5



Delphi Technologies, Inc., Troy, Mi




FIG. 6





FIG. 7



Delphi Technologies, Inc., Troy, MI

6/11



CONTACT BETWEEN THE GROOVE OF THE HOUSING AND THE OUTER ROLLER AT THE OPPOSITE SIDE OF THE LOADED SIDE






FIG. 9



Delphi Technologies, Inc., Troy, Mi







Delphi Technologies, Inc., Troy, MI




FIG. 12





FIG. 13



Delphi Technologies, Inc., Troy, Mil






FIG. 15



Delphi Technologies, Inc., Troy, Mi




FIG. 16
PRIOR ART




FIG. 17



Delphi Technologies, Inc., Troy, Mi

